Internal Photos







RISK OF FIRE—REPLACE AS
100-120:4A
125V OR 250V
PRIMARY
SECONDARY
K0732S 4V8
81291184
23V42C13


POWER
SECONDARY
DANGER!
MAIN
VOLTAGE
PRIMARY

CODE DVR-R09OR
MFD. APRIL 2005
SER. NO. EDDL019718WL
DVR-R09OR
12V 1.0A
5V 1.6A


ZORAN
ZR35100PQCG
B0 TS4AM0429CE
Activa™100
ZORAN
ZR36750BGCG-V
F0 TS4DM0450FE
Activa™150
REFLOW
NTSC/PAL
ENC
TOP


REFLOW
& POINT DIP
BOT
ROM
MEMO