9.6.3. 802.11ax HE80 MODE IN THE UNII-5 BAND

Antenna 6: 26-Tones, RU Index 0



LOW CHANNEL 5985

MID CHANNEL 6145

HIGH CHANNEL 6385

UL VERIFICATION SERVICES
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

Antenna 6: 26-Tones, RU Index 18



LOW CHANNEL 5985

MID CHANNEL 6145



HIGH CHANNEL 6385

UL VERIFICATION SERVICES
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

Antenna 6: 26-Tones, RU Index 36



LOW CHANNEL 5985

MID CHANNEL 6145



HIGH CHANNEL 6385

Antenna 6: SU MODE



LOW CHANNEL 5985



MID CHANNEL 6145



HIGH CHANNEL 6385

Antenna 5: 26-Tones, RU Index 0

LOW CHANNEL 5985



MID CHANNEL 6145



HIGH CHANNEL 6385

UL VERIFICATION SERVICES
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

Antenna 5: 26-Tones, RU Index 18

LOW CHANNEL 5985

MID CHANNEL 6145

HIGH CHANNEL 6385

Antenna 5: 26-Tones, RU Index 36



LOW CHANNEL 5985

MID CHANNEL 6145



HIGH CHANNEL 6385

UL VERIFICATION SERVICES
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

Antenna 5: SU MODE



LOW CHANNEL 5985



MID CHANNEL 6145



HIGH CHANNEL 6385

Antenna 6 + Antenna 5 OFDMA MODE: 26-Tones, RU Index 0

LOW CHANNEL ANT 6 5985



LOW CHANNEL ANT 5 5985



MID CHANNEL ANT 6 6145



MID CHANNEL ANT 5 6145



HIGH CHANNEL ANT 6 6385



HIGH CHANNEL ANT 5 6385

UL VERIFICATION SERVICES
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

Antenna 6 + Antenna 5 OFDMA MODE: 26-Tones, RU Index 18

LOW CHANNEL ANT 6 5985



LOW CHANNEL ANT 5 5985

MID CHANNEL ANT 6 6145

MID CHANNEL ANT 5 6145



HIGH CHANNEL ANT 6 6385



HIGH CHANNEL ANT 5 6385

UL VERIFICATION SERVICES
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

Antenna 6 + Antenna 5 OFDMA MODE: 26-Tones, RU Index 36



LOW CHANNEL ANT 6 5985



LOW CHANNEL ANT 5 5985



MID CHANNEL ANT 6 6145



MID CHANNEL ANT 5 6145



HIGH CHANNEL ANT 6385

HIGH CHANNEL ANT 5 6385

UL VERIFICATION SERVICES
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

Antenna 6 + Antenna 5 OFDMA MODE: SU



LOW CHANNEL ANT 6 5985



LOW CHANNEL ANT 5 5985



MID CHANNEL ANT 6 6145



MID CHANNEL ANT 5 6145

HIGH CHANNEL ANT 6 6385



HIGH CHANNEL ANT 5 6385

9.6.4. 802.11ax HE160 MODE IN THE UNII-5 BAND

Antenna 6: 26-Tones, RU Index 0

LOW CHANNEL 6025



MID CHANNEL 6185



HIGH CHANNEL 6345

Antenna 6: 26-Tones, RU Index 36



LOW CHANNEL 6025



MID CHANNEL 6185



HIGH CHANNEL 6345

UL VERIFICATION SERVICES
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

Antenna 6: 26-Tones, S36



LOW CHANNEL 6025



MID CHANNEL 6185



HIGH CHANNEL 6345

UL VERIFICATION SERVICES
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

Antenna 6: SU MODE

LOW CHANNEL 6025



MID CHANNEL 6185



HIGH CHANNEL 6345

Antenna 5: 26-Tones, RU Index 0

LOW CHANNEL 6025



MID CHANNEL 6185



HIGH CHANNEL 6345

Antenna 5: 26-Tones, RU Index 36



LOW CHANNEL 6025



MID CHANNEL 6185



HIGH CHANNEL 6345

UL VERIFICATION SERVICES
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

Antenna 5: 26-Tones, S36



LOW CHANNEL 6025



MID CHANNEL 6185



HIGH CHANNEL 6345

Antenna 5: SU MODE

LOW CHANNEL 6025



MID CHANNEL 6185



HIGH CHANNEL 6345

UL VERIFICATION SERVICES
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

Antenna 6 + Antenna 5 OFDMA MODE: 26-Tones, RU Index 0

LOW CHANNEL ANT 6 6025



LOW CHANNEL ANT 5 6025



MID CHANNEL ANT 6 6185



MID CHANNEL ANT 5 6185



HIGH CHANNEL ANT 6 6345



HIGH CHANNEL ANT 5 6345

UL VERIFICATION SERVICES
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

Antenna 6 + Antenna 5 OFDMA MODE: 26-Tones, RU Index 36



LOW CHANNEL ANT 6 6025



LOW CHANNEL ANT 5 6025



MID CHANNEL ANT 6 6185



MID CHANNEL ANT 5 6185



HIGH CHANNEL ANT 6 6345



HIGH CHANNEL ANT 5 6345

UL VERIFICATION SERVICES
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

Antenna 6 + Antenna 5 OFDMA MODE: 26-Tones, S36



LOW CHANNEL ANT 6 6025



LOW CHANNEL ANT 5 6025



MID CHANNEL ANT 6 6185



MID CHANNEL ANT 5 6185



HIGH CHANNEL ANT 6 6345



HIGH CHANNEL ANT 5 6345

Antenna 6 + Antenna 5 OFDMA MODE: SU



LOW CHANNEL ANT 6 6025



LOW CHANNEL ANT 5 6025



MID CHANNEL ANT 6 6185



MID CHANNEL ANT 5 6185



HIGH CHANNEL ANT 6 6345



HIGH CHANNEL ANT 5 6345

9.6.5. 802.11ax HE20 MODE IN THE UNII-7 BAND

Antenna 6: 26-Tones, RU Index 0

LOW CHANNEL 6535

MID CHANNEL 6715



HIGH CHANNEL 6855

Antenna 6: 26-Tones, RU Index 4

LOW CHANNEL 6535

MID CHANNEL 6715



HIGH CHANNEL 6855

Antenna 6: 26-Tones, RU Index 8

LOW CHANNEL 6535



MID CHANNEL 6715

HIGH CHANNEL 6855

UL VERIFICATION SERVICES
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

Antenna 5: 26-Tones, SU Mode

LOW CHANNEL 6535



MID CHANNEL 6715



HIGH CHANNEL 6855

Antenna 5: 26-Tones, RU Index 0

LOW CHANNEL 6535

MID CHANNEL 6715



HIGH CHANNEL 6855

UL VERIFICATION SERVICES
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

Antenna 5: 26-Tones, RU Index 4

LOW CHANNEL 6535

MID CHANNEL 6715



HIGH CHANNEL 6855

Antenna 5: 26-Tones, RU Index 8

LOW CHANNEL 6535

MID CHANNEL 6715

HIGH CHANNEL 6855

Antenna 5: 26-Tones, SU Mode



LOW CHANNEL 6535



MID CHANNEL 6715



HIGH CHANNEL 6855