Schumi 34_LP

| Program Name | Series | Size |
|---|---|---|
| **Schumi** | | **34”** |
| Revision List | | |
| Date/Init. | Comment | |
| 09022016 | Currected bottom view | |
| 07182016 | Initial release | |
















**Note:**
**This is inside the unit.**

Reserve location for service team use:
*Factory does NOT put label here.
813180-002 service label to be relocated from inside of chassis to this location only if critical information on regulatory label is damaged beyond legibility during a failed service event. Intention is that that main regulatory label will not be damaged during a service event – it should be carefully removed with heat and a scraper, and then re-applied without damage (use additional adhesive if necessary to prevent peeling).






7265NGW+180W




7265NGW+230W




3168NGW+180W




3168NGW+230W