HP

1

EN
A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **FR**

AR
A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **HR**

ID
A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **IT**

BG
A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **KK**

CS
A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **LV**

DA
A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **LT**

DE
A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **HU**

EL
A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **NL**

ES
A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **NO**

A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **PL**

A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **PT**

A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **BR**

A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **RO**

A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **RU**

A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **SK**

A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **SL**

A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **FI**

A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **SR**

A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **SE**

A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **TH**

A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **TR**

A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **UK**

A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **JA**

A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **KO**

A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **CN**

A. Select **Start**, select **Windows Update**, select **Check for updates**, and then install any updates. Restart the computer, if necessary.
B. Select **Start**, and then select **Mixed Reality Portal**.
C. Follow the on-screen instructions. **TW**

2

3

4
SS⟶
MINIDP

5*
① ②

6
2s

7
① 3s ② DEVICES**
HP VR

8

9
① ②

10
2s

11
① 3s ② DEVICES**
HP VR

12

EN *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

AR *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

ID *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

BG *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

CS *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

DA *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

DE *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

ES *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

EL *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

FR *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

HR *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

IT *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

KK *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

LV *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

LT *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

HU *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

NL *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

NO *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

PL *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

PT *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

BR *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

RO *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

RU *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

SK *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

SL *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

FI *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

SR *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

SE *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

TH *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

TR *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

UK *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

JA *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

KO *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

CN *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

TW *LCD refresh rate: Hybrid 60/90 Hz
• High refresh rate with maximum fidelity on PCs that support DisplayPort 1.3.
• Maximum 60 Hz refresh rate on PCs that support DisplayPort 1.2.
For more information, go to http://www.hp.com/go/mixedreality/Support.

1
2
3
4

5

6
7

8

9

HR
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

NO
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

SL
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

JA
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

IT
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

PL
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

FI
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

KO
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

KK
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

PT
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

SR
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

CN
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

LV
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

BR
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

SE
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

TW
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

EN
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

DA
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

LT
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

RO
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

TH
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

AR
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

DE
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

HU
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

RU
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

TR
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

ID
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

ES
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

NL
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

SK
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

UK
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

BG
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

EL
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

CS
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.

FR
1 Thumbstick (Teleport, Rotate)*
2 Menu button
3 TouchPad*
4 Windows® button
5 Trigger (Select)
6 Grab button (Grasp)
7 Lights
  Quickly blinking: Pairing mode
  Slowly blinking: Idle mode
  Blinking (2 times): Low battery level
  Blinking (3 times): Critical battery level
8 Microphones (2)
9 Activity light
  On: Headset is on.
  * Make your gesture and then press to execute your action.