

1




FCC ID: L4PK8500MX15

Reference modification letter: No.1

832741


1



FCC ID: L4PK8500MX15


Reference modification letter: No.6

832741




FCC ID: L4PK8500MX15
Front side of INVERTER

832741




FCC ID: L4PK8500MX15
Rear side of INVERTER



832741


FCC ID: L4PK8500MX15
Reference modification letter: No.2



832741


FCC ID: L4PK8500MX15

Reference modification letter: No.2




832741

FCC ID: L4PK8500MX15
Mechanical construction




FCC ID: L4PK8500MX15

Mechanical construction




832741

FCC ID: L4PK8500MX15
Front side of TOUCH PAD




832741

FCC ID: L4PK8500MX15
Rear side of TOUCH PAD



832741

FCC ID: L4PK8500MX15
Mechanical construction



832741


FCC ID: L4PK8500MX15
Mechanical construction

FCC ID: L4PK8500MX15

FAN


FCC ID LABEL

832741




FCC ID: L4PK8500MX15
Mechanical construction

832741




21




FCC ID: L4PK8500MX15

Reference modification letter: No.1



FCC ID: L4PK8500MX15
Mechanical construction





FCC ID: L4PK8500MX15
Reference modification letter: No.1

2A

832741


FCC ID: L4PK8500MX15
Main board & DC/DC & CPU MODULE






832741

FCC ID: L4PK8500MX15
Front side of main board
Reference modification letter: No.3,4,5




832741

FCC ID: L4PK8500MX15
Rear side of main board




832741

FCC ID: L4PK8500MX15
Front side of DC/DC BOARD




832741

FCC ID: L4PK8500MX15
Rear side of DC/DC board




832741

FCC ID: L4PK8500MX15
Front side of CPU BOARD




832741

FCC ID: L4PK8500MX15
Rear side of CPU board




832741

FCC ID: L4PK8500MX15
Front side of RAM




832741

FCC ID: L4PK8500MX15
Rear side of RAM



832741


FCC ID: L4PK8500MX15
Front side of power switch & LED board



832741

FCC ID: L4PK8500MX15


Rear side of power switch & LED board



832741

FCC ID: L4PK8500MX15
Reference modification letter: No.1


2A



832741


FCC ID: L4PK8500MX15
Mechanical construction

43




832741

FCC ID: L4PK8500MX15
Mechanical construction




832741

FCC ID: L4PK8500MX15
Front side of CD-ROM




832741

FCC ID: L4PK8500MX15
Mechanical construction




832741

FCC ID: L4PK8500MX15
Reference modification letter: No.1




832741

FCC ID: LAPK8500MX15
Reference modification letter: No.1



832741



FCC ID: L4PK8500MX15
Mechanical constriction




832741

STANLEY 30-2000-0007-01
1874200-01
4000001
CEC
CERTIFICATION
CLASS 1 LASER PRODUCT
LASER KLASSE 1

FCC ID: LAFK8500MX15
Mechanical construction





832741




FCC ID: LAPK8500MK15
Mechanical construction (ADAPTER)

832741




FCC ID: L4PK8500MX15
Mechanical construction (Adapter)

832741




FCC ID: LAPK8500MX15
Mechanical construction (Adapter)

832741



FCC ID: L4PK8500MX15
Front side of main board
(Adapter)



832741

FCC ID: L4PK8500MX15
Rear side of main board (Adapter)