Annex E: Test Setup Photos

	Document	Page
RIM Testing Services™	**Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RCN72UW**	**2(5)**

Author Data	Dates of Test	Report No	FCC ID
Daoud Attayi	**June 28-30, 2010**	**RTS-1689-1007-36**	**L6ARCN70UW**

Figure 1 - BlackBerry® Smartphone

|	**Document**	**Page**
RIM Testing Services™	**Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RCN72UW**	**3(5)**

Author Data **Daoud Attayi**	Dates of Test **June 28-30, 2010**	Report No **RTS-1689-1007-36**	FCC ID **L6ARCN70UW**

Figure 2: Probe calibration and reference signal measurement setup

	Document	**Page**
RIM Testing Services™	**Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM)** **T-Coil Test Report for BlackBerry® Smartphone model RCN72UW**	**4(5)**

| **Author Data** **Daoud Attayi**	Dates of Test **June 28-30, 2010**	Report No **RTS-1689-1007-36**	FCC ID **L6ARCN70UW**

Figure 3: Ambient noise and system validation measurement setup

Figure 4: Audio Band Magnetic (ABM) T-Coil measurement setup