Revised board:




2F08380B-01 REV.0 M
AOI-P
105734-03
105734-03

Revised board with shields removed: