

98 mS Pulse Train



19 Total Pulses

1 Large Pulse

4 Medium Pulses

14 Small Pulses



Large pulse = 3 mS



Medium Pule = 600 uS



Small pulse = 360 uS

1 Large Pulse	=	1 * 3 mS	= 3 mS
4 Medium Pulses	=	4 * 600 uS	= 2.4 mS
14 Small Pulses	=	14 * 360 uS	= 5.04 mS

10.44 mS on-time / 98 mS = 10.65 % Duty Cycle