Changes from TLG-RS232 (LF80_RDC):

Due to end of live of the µ-controller µPSD3333-D-40U6, we were force to integrate a new µ-controller in our TLG RS232 hardware.
The device "µPSD3333-D-40U6" are replaced by "LM3S6965-IQC50-A2".
With this change the name TLG-RS232 gets an addition LF80_RDC

Label:

www.brooks-rfid.com   C€

FCC ID N5GTSG
Ser.Nr.: 1106MIS12051
Type: TLG-RS232

Made in Germany

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: 1) this device may not cause harmful interference, and 2) this device must accept any interference received, including interference that may cause undesired operation.