Helen Zhao

Subject: FW: Sierra Wireless Inc., FCC ID: N7NMC8781U, Assessment NO.: AN07T6861, Notice#1

MC878x__Tune up MC878X_Schematic
   procedure.pdf   s.pdf

From: September Radecki
Sent: Thursday, May 31, 2007 3:31 PM
To: Helen Zhao
Cc: Barbara Judge; Michael Heckrotte
Subject: RE: Sierra Wireless Inc., FCC ID: N7NMC8781U, Assessment NO.:
AN07T6861, Notice#1

Hi Helen,

Here are the answers to your questions on the above application:

Question #1: The Tune-up procedure of AC881U refers the Tune-up
Procedure of MC8781:

The procedure for the Tune-up of the MC8781 module is included for
reference. Please see
¡°MC8781 Multi-Mode & Multi-Band Wireless Network Module Tune up
procedure¡±.

But the Tune-up Procedure of MC8781 was not submitted. Please upload the
file asap.
<CCS Answer:> Please see attached tune-up procedure.

Question #2: The Schematic diagram in the filing is just a one-page
system integration schematic. Please submit the module schematics.
<CCS Answer:> Please see attached schematic.

Thank you.

Best regards,
September