
D
C
B
A
8
7
6
5
4
3
2
1
ECO # | REV | DATE | DESCRIPTION
???? | A2 | 3-27-00 | Added PD2 & PD3 to U28
1785 | A2 | 1-6-00 | BICOM changes: swapped pins RP35, RP40 REFCLK
AMERICAN TEL-A-SY
4800 CURTIN
MCFARLAND, WISCO
(608)838-4
TITLE: H.110 BRI S/T INT
DOCUMENT NUMBER: 2588000
DATE: 12 JULY 1999