FCC ID:PIDASMAX700

<u>**EasyST/ ProST 700 MHz Tune up procedure**</u>

Each EasyST/ProST radio has been tested by automatic test station. As part of the test , the Maximum RF output power value has been masured. In case the RF output power is higher then specified in the System Description, the EasyST/ProST radio doesn't pass the test and get Fail status.
EasyST/ProST boards with Fail status can not be assembled as part of final product.

Name of authorized person: Zion Levy
Position: Compliances & Testing Engineer

Date: January 25, 2009