6. Foto Report

**Picture 1   : Top side of module (with case)**

Picture 2   : Top side of module (without case)