5755MHz



5795MHz



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

802.11ac80 Mode

5210MHz



5755MHz



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

6.5.2. 2TX MODE

Mode	Channel	Antenna	PSD		Limit
			Single	Total	
a	5180	B	-8.136	-4.95	8.5
		C	-7.78		8.5
	5200	B	-7.34	-4.46	8.5
		C	-7.614		8.5
	5240	B	-7.684	-4.75	8.5
		C	-7.841		8.5
	5745	B	5.055	7.95	21.5
		C	4.815		21.5
	5785	B	3.98	7.54	21.5
		C	5.016		21.5
	5825	B	3.594	7.76	21.5
		C	5.668		21.5
n20	5180	B	-8.188	-5.05	8.5
		C	-7.927		8.5
	5200	B	-7.807	-4.77	8.5
		C	-7.753		8.5
	5240	B	-7.816	-5.04	8.5
		C	-8.296		8.5
	5745	B	5.235	8.15	21.5
		C	5.032		21.5
	5785	B	3.641	6.99	21.5
		C	4.298		21.5
	5825	B	3.364	7.44	21.5
		C	5.293		21.5
ac20	5180	B	-8.265	-5.03	8.5
		C	-7.818		8.5
	5200	B	-7.513	-4.59	8.5
		C	-7.701		8.5
	5240	B	-7.741	-5.03	8.5
		C	-7.818		8.5
	5745	B	4.659	7.92	21.5
		C	5.155		21.5
	5785	B	3.71	7.12	21.5

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

		C	4.469		21.5
	5825	B	3.954	7.87	21.5
		C	5.619		21.5
n40	5190	B	-10.925	-7.8	8.5
		C	-10.699		8.5
	5230	B	-11.003	-7.91	8.5
		C	-10.834		8.5
	5755	B	0.948	3.98	21.5
		C	0.998		21.5
	5795	B	-0.384	3.12	21.5
		C	0.551		21.5
ac40	5190	B	-10.37	-7.22	8.5
		C	-10.093		8.5
	5230	B	-10.17	-7.39	8.5
		C	-10.636		8.5
	5755	B	1.129	4.12	21.5
		C	1.093		21.5
	5795	B	-0.185	3.24	21.5
		C	0.61		21.5
AC80	5210	B	-13.441	-10.16	8.5
		C	-12.918		8.5
	5775	B	-3.364	-0.67	21.5
		C	-4.033		21.5

Note: All the antenna ports had been tested, but only the worst data recorded in the report.

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

TEST PLOT FOR ANTENNA B AND C

802.11a Mode

5180MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

5200MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

5240MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

5745MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

5785MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

5825MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

802.11 n20 Mode

5180MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

5200MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

5240MHz





5745MHz

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

5785MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

5825MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

802.11n40 Mode

5190MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

5230MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

5755MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

5795MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

802.11 ac20 Mode

5180MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

5200MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

5240MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

5745MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

5785MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

5825MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

802.11ac40 Mode

5190MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

5230MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

5755MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

5795MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

802.11ac80 Mode

5210MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

5775MHz





This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.