11N40MIMO_Ant2_5755

11N40MIMO_Ant1_5795

11N40MIMO_Ant2_5795

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AC20MIMO_Ant1_5180

11AC20MIMO_Ant2_5180

11AC20MIMO_Ant1_5200

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AC20MIMO_Ant2_5200

11AC20MIMO_Ant1_5240


11AC20MIMO_Ant2_5240

11AC20MIMO_Ant1_5260

11AC20MIMO_Ant2_5260

11AC20MIMO_Ant1_5280

11AC20MIMO_Ant2_5280

11AC20MIMO_Ant1_5320

11AC20MIMO_Ant2_5320

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AC20MIMO_Ant1_5500

11AC20MIMO_Ant2_5500

11AC20MIMO_Ant1_5580

11AC20MIMO_Ant2_5580

11AC20MIMO_Ant1_5700

11AC20MIMO_Ant2_5700

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AC20MIMO_Ant1_5720_UNII-2C

11AC20MIMO_Ant2_5720_UNII-2C

11AC20MIMO_Ant1_5720_UNII-3

11AC20MIMO_Ant2_5720_UNII-3

11AC20MIMO_Ant1_5745

11AC20MIMO_Ant2_5745

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AC20MIMO_Ant1_5785

11AC20MIMO_Ant2_5785

11AC20MIMO_Ant1_5825

11AC20MIMO_Ant2_5825

11AC40MIMO_Ant1_5190

11AC40MIMO_Ant2_5190

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AC40MIMO_Ant1_5230

11AC40MIMO_Ant2_5230

11AC40MIMO_Ant1_5270

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AC40MIMO_Ant2_5270

11AC40MIMO_Ant1_5310

11AC40MIMO_Ant2_5310

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AC40MIMO_Ant1_5510


11AC40MIMO_Ant2_5510

11AC40MIMO_Ant1_5550

11AC40MIMO_Ant2_5550

11AC40MIMO_Ant1_5670

11AC40MIMO_Ant2_5670

11AC40MIMO_Ant1_5710_UNII-2C

11AC40MIMO_Ant2_5710_UNII-2C

11AC40MIMO_Ant1_5710_UNII-3

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AC40MIMO_Ant2_5710_UNII-3

11AC40MIMO_Ant1_5755

11AC40MIMO_Ant2_5755

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AC40MIMO_Ant1_5795

11AC40MIMO_Ant2_5795

11AC80MIMO_Ant1_5210

11AC80MIMO_Ant2_5210

11AC80MIMO_Ant1_5290


11AC80MIMO_Ant2_5290

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AC80MIMO_Ant1_5530

11AC80MIMO_Ant2_5530

11AC80MIMO_Ant1_5610

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AC80MIMO_Ant2_5610

11AC80MIMO_Ant1_5690_UNII-2C


11AC80MIMO_Ant2_5690_UNII-2C

11AC80MIMO_Ant1_5690_UNII-3

11AC80MIMO_Ant2_5690_UNII-3

11AC80MIMO_Ant1_5775

11AC80MIMO_Ant2_5775

12.6. Appendix D: Duty Cycle
12.6.1. Test Result

Mode	On Time (msec)	Period (msec)	Duty Cycle x (Linear)	Duty Cycle (%)	Duty Cycle Correction Factor (dB)	1/T Minimum VBW (kHz)	Final setting For VBW (kHz)
11A MIMO	2.07	2.25	0.9200	92.00	0.36	0.48	0.5
11AC20 MIMO	1.93	2.03	0.9507	95.07	0.22	0.52	1
11AC40 MIMO	0.95	1.09	0.8716	87.16	0.60	1.05	2
11AC80 MIMO	0.46	0.60	0.7667	76.67	1.15	2.17	3

Note:
Duty Cycle Correction Factor=10log (1/x).
Where: x is Duty Cycle (Linear)
Where: T is On Time
If that calculated VBW is not available on the analyzer then the next higher value should be used.