Internal Photo






50
40
30
20
10
mm
70
60
50
40
30
20
10


GND
TP2
R15
Q2
C22
R13
C10
C18
BC352
239AU
624AA
AZR
56W
7A9L


WARNING:
Fire, Explosion,
And Severe Burn
Hazard.
Do Not Recharge,
Crush, Disassemble,
Heat Above
Or Incinerate.(**)
mm


MS P/N:X808059 – 002
WARNING:
Fire, Explosion,
And Severe Burn
Hazard.
Do Not Recharge,
Crush, Disassemble,
Heat Above
Or Incinerate.(**)
mm


mm


TJ-I 94V-0
0705 E201363
MMS-7301 V4R6
2007.01.23
TP8
TP6
TP5
TP7
TP3
RX
TX
TP12
TP13
TP9
TP4
TP10
TP11
TP1
SW1
X3
L5
X4
X5
J1
5V
GND
CSB
MOSI
MISO
CLK


MS P/N:X808059 – 002
WARNING:
Fire, Explosion,
And Severe Burn
Hazard.
Do Not Recharge,
Crush, Disassemble,
Heat Above
(100℃/212℉),
Or Incinerate.(++)
30 20 10 mm
10 20 30 40


B6210128J
30 20 10 mm
10 20 30 40

Dock Photo






mm


mm


30
20
10
mm
10
20
30
40

USB Cable Photo