During manufacturing, the AP 8120 is programmed with the US country code that limits the channel selection to only those channels allowed in the US.

Once set in manufacturing, the end-user interface does not allow changing of the country code.