80MHz

QPSK

QPSK Low channel FRB

QPSK Low channel 1RB_Offset Low



QPSK Low channel 1RB_Offset High



QPSK Mid channel FRB



QPSK Mid channel 1RB_Offset Low



QPSK Mid channel 1RB_Offset High

UL Korea, Ltd. Suwon Laboratory FORM ID: FCC_24/27(04)
218 Maeyeong-ro, Yeongtong-gu, Suwon-si, Gyeonggi-do, 16675, Korea TEL: (031) 337-9902 FAX: (031) 213-5433

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

80MHz

QPSK

QPSK High channel FRB



QPSK High channel 1RB_Offset Low



QPSK High channel 1RB_Offset High

80MHz

16QAM



16QAM Low channel FRB



16QAM Low channel 1RB_Offset Low



16QAM Low channel 1RB_Offset High

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

80MHz

16QAM

16QAM Mid channel FRB

16QAM Mid channel 1RB_Offset Low



16QAM Mid channel 1RB_Offset High



16QAM High channel FRB



16QAM High channel 1RB_Offset Low



16QAM High channel 1RB_Offset High

UL Korea, Ltd. Suwon Laboratory FORM ID: FCC_24/27(04)
218 Maeyeong-ro, Yeongtong-gu, Suwon-si, Gyeonggi-do, 16675, Korea TEL: (031) 337-9902 FAX: (031) 213-5433

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

60MHz

QPSK



QPSK Low channel FRB

QPSK Low channel 1RB_Offset Low



QPSK Low channel 1RB_Offset High



QPSK Mid channel FRB



QPSK Mid channel 1RB_Offset Low



QPSK Mid channel 1RB_Offset High

UL Korea, Ltd. Suwon Laboratory FORM ID: FCC_24/27(04)
218 Maeyeong-ro, Yeongtong-gu, Suwon-si, Gyeonggi-do, 16675, Korea TEL: (031) 337-9902 FAX: (031) 213-5433

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

60MHz

QPSK

QPSK High channel FRB



QPSK High channel 1RB_Offset Low



QPSK High channel 1RB_Offset High

60MHz

16QAM



16QAM Low channel FRB



16QAM Low channel 1RB_Offset Low



16QAM Low channel 1RB_Offset High

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

60MHz

16QAM

16QAM Mid channel FRB

16QAM Mid channel 1RB_Offset Low



16QAM Mid channel 1RB_Offset High



16QAM High channel FRB



16QAM High channel 1RB_Offset Low



16QAM High channel 1RB_Offset High

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

50MHz

QPSK



QPSK Low channel FRB



QPSK Low channel 1RB_Offset Low



QPSK Low channel 1RB_Offset High



QPSK Mid channel FRB



QPSK Mid channel 1RB_Offset Low



QPSK Mid channel 1RB_Offset High

UL Korea, Ltd. Suwon Laboratory FORM ID: FCC_24/27(04)
218 Maeyeong-ro, Yeongtong-gu, Suwon-si, Gyeonggi-do, 16675, Korea TEL: (031) 337-9902 FAX: (031) 213-5433

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

50MHz

QPSK

QPSK High channel FRB

QPSK High channel 1RB_Offset Low



QPSK High channel 1RB_Offset High

50MHz

16QAM



16QAM Low channel FRB



16QAM Low channel 1RB_Offset Low



16QAM Low channel 1RB_Offset High

UL Korea, Ltd. Suwon Laboratory FORM ID: FCC_24/27(04)
218 Maeyeong-ro, Yeongtong-gu, Suwon-si, Gyeonggi-do, 16675, Korea TEL: (031) 337-9902 FAX: (031) 213-5433

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

50MHz

16QAM

16QAM Mid channel FRB



16QAM Mid channel 1RB_Offset Low



16QAM Mid channel 1RB_Offset High



16QAM High channel FRB



16QAM High channel 1RB_Offset Low



16QAM High channel 1RB_Offset High

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

40MHz

QPSK

QPSK Low channel FRB



QPSK Low channel 1RB_Offset Low



QPSK Low channel 1RB_Offset High



QPSK Mid channel FRB



QPSK Mid channel 1RB_Offset Low



QPSK Mid channel 1RB_Offset High

UL Korea, Ltd. Suwon Laboratory FORM ID: FCC_24/27(04)
218 Maeyeong-ro, Yeongtong-gu, Suwon-si, Gyeonggi-do, 16675, Korea TEL: (031) 337-9902 FAX: (031) 213-5433

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

40MHz

QPSK

QPSK High channel FRB

QPSK High channel 1RB_Offset Low



QPSK High channel 1RB_Offset High

40MHz

16QAM



16QAM Low channel FRB



16QAM Low channel 1RB_Offset Low



16QAM Low channel 1RB_Offset High

UL Korea, Ltd. Suwon Laboratory FORM ID: FCC_24/27(04)
218 Maeyeong-ro, Yeongtong-gu, Suwon-si, Gyeonggi-do, 16675, Korea TEL: (031) 337-9902 FAX: (031) 213-5433

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

40MHz

16QAM

16QAM Mid channel FRB



16QAM Mid channel 1RB_Offset Low



16QAM Mid channel 1RB_Offset High



16QAM High channel FRB



16QAM High channel 1RB_Offset Low



16QAM High channel 1RB_Offset High

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

30MHz

QPSK



QPSK Low channel FRB



QPSK Low channel 1RB_Offset Low



QPSK Low channel 1RB_Offset High

QPSK Mid channel FRB



QPSK Mid channel 1RB_Offset Low



QPSK Mid channel 1RB_Offset High

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

30MHz

QPSK

QPSK High channel FRB

QPSK High channel 1RB_Offset Low



QPSK High channel 1RB_Offset High

30MHz

16QAM



16QAM Low channel FRB



16QAM Low channel 1RB_Offset Low



16QAM Low channel 1RB_Offset High

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.