80MHz

16QAM

16QAM Mid channel FRB

16QAM Mid channel 1RB_Offset Low



16QAM Mid channel 1RB_Offset High



16QAM High channel FRB



16QAM High channel 1RB_Offset Low



16QAM High channel 1RB_Offset High

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

70MHz

BPSK

BPSK Low channel FRB



BPSK Low channel 1RB_Offset Low



BPSK Low channel 1RB_Offset High



BPSK Mid channel FRB



BPSK Mid channel 1RB_Offset Low



BPSK Mid channel 1RB_Offset High

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

70MHz

BPSK

BPSK High channel FRB



BPSK High channel 1RB_Offset Low



BPSK High channel 1RB_Offset High

70MHz

16QAM



16QAM Low channel FRB



16QAM Low channel 1RB_Offset Low



16QAM Low channel 1RB_Offset High

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

70MHz

16QAM

16QAM Mid channel FRB



16QAM Mid channel 1RB_Offset Low



16QAM Mid channel 1RB_Offset High



16QAM High channel FRB



16QAM High channel 1RB_Offset Low



16QAM High channel 1RB_Offset High

UL Korea, Ltd. Suwon Laboratory FORM ID: FCC_22/24/27/90(04)
218 Maeyeong-ro, Yeongtong-gu, Suwon-si, Gyeonggi-do, 16675, Korea TEL: (031) 337-9902 FAX: (031) 213-5433
UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

60MHz

BPSK

BPSK Low channel FRB

BPSK Low channel 1RB_Offset Low



BPSK Low channel 1RB_Offset High



BPSK Mid channel FRB



BPSK Mid channel 1RB_Offset Low



BPSK Mid channel 1RB_Offset High

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

60MHz

BPSK

BPSK High channel FRB

BPSK High channel 1RB_Offset Low



BPSK High channel 1RB_Offset High

60MHz

16QAM



16QAM Low channel FRB



16QAM Low channel 1RB_Offset Low



16QAM Low channel 1RB_Offset High

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

60MHz

16QAM

16QAM Mid channel FRB



16QAM Mid channel 1RB_Offset Low



16QAM Mid channel 1RB_Offset High



16QAM High channel FRB



16QAM High channel 1RB_Offset Low



16QAM High channel 1RB_Offset High

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

50MHz

BPSK

BPSK Low channel FRB



BPSK Low channel 1RB_Offset Low

BPSK Low channel 1RB_Offset High



BPSK Mid channel FRB



BPSK Mid channel 1RB_Offset Low



BPSK Mid channel 1RB_Offset High

UL Korea, Ltd. Suwon Laboratory FORM ID: FCC_22/24/27/90(04)
218 Maeyeong-ro, Yeongtong-gu, Suwon-si, Gyeonggi-do, 16675, Korea TEL: (031) 337-9902 FAX: (031) 213-5433

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

50MHz

BPSK

BPSK High channel FRB

BPSK High channel 1RB_Offset Low



BPSK High channel 1RB_Offset High

50MHz

16QAM



16QAM Low channel FRB



16QAM Low channel 1RB_Offset Low



16QAM Low channel 1RB_Offset High

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

50MHz

16QAM

16QAM Mid channel FRB

16QAM Mid channel 1RB_Offset Low



16QAM Mid channel 1RB_Offset High



16QAM High channel FRB



16QAM High channel 1RB_Offset Low



16QAM High channel 1RB_Offset High

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

40MHz

BPSK

BPSK Low channel FRB

BPSK Low channel 1RB_Offset Low



BPSK Low channel 1RB_Offset High



BPSK Mid channel FRB



BPSK Mid channel 1RB_Offset Low



BPSK Mid channel 1RB_Offset High

UL Korea, Ltd. Suwon Laboratory FORM ID: FCC_22/24/27/90(04)
218 Maeyeong-ro, Yeongtong-gu, Suwon-si, Gyeonggi-do, 16675, Korea TEL: (031) 337-9902 FAX: (031) 213-5433
UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

40MHz

BPSK

BPSK High channel FRB

BPSK High channel 1RB_Offset Low



BPSK High channel 1RB_Offset High

40MHz

16QAM

16QAM Low channel FRB



16QAM Low channel 1RB_Offset Low



16QAM Low channel 1RB_Offset High

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

40MHz

16QAM

16QAM Mid channel FRB

16QAM Mid channel 1RB_Offset Low



16QAM Mid channel 1RB_Offset High



16QAM High channel FRB



16QAM High channel 1RB_Offset Low



16QAM High channel 1RB_Offset High

UL Korea, Ltd. Suwon Laboratory FORM ID: FCC_22/24/27/90(04)
218 Maeyeong-ro, Yeongtong-gu, Suwon-si, Gyeonggi-do, 16675, Korea TEL: (031) 337-9902 FAX: (031) 213-5433

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

30MHz

BPSK

BPSK Low channel FRB

BPSK Low channel 1RB_Offset Low

BPSK Low channel 1RB_Offset High



BPSK Mid channel FRB



BPSK Mid channel 1RB_Offset Low



BPSK Mid channel 1RB_Offset High

UL Korea, Ltd. Suwon Laboratory FORM ID: FCC_22/24/27/90(04)
218 Maeyeong-ro, Yeongtong-gu, Suwon-si, Gyeonggi-do, 16675, Korea TEL: (031) 337-9902 FAX: (031) 213-5433
UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.

30MHz

BPSK

BPSK High channel FRB

BPSK High channel 1RB_Offset Low



BPSK High channel 1RB_Offset High

30MHz

16QAM



16QAM Low channel FRB



16QAM Low channel 1RB_Offset Low



16QAM Low channel 1RB_Offset High

UL Korea, Ltd. Suwon Laboratory FORM ID: FCC_22/24/27/90(04)
218 Maeyeong-ro, Yeongtong-gu, Suwon-si, Gyeonggi-do, 16675, Korea TEL: (031) 337-9902 FAX: (031) 213-5433

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.