

From: Kimberly.Mai@faa.gov
To: [Thorsheim, Joel D](mailto:Thorsheim,Joel.D)
Cc: Mark.R.Gallant@faa.gov
Subject: Re: FCC Call Sign WE2XQQ Renewal FAA Coordination Request
Date: Friday, January 27, 2012 11:09:43 AM

Joe Thorsheim:

The coordination for Roswell, NM is NG T120076 and excluding the 5250-5825 MHz band.

Best Regards,

Kimberly Mai
AJW-936, Central Service Area
Spectrum Engineering Team
(817)222-4765 - Phone
(817)222-5925 - Fax

From: Mark R Gallant/ASW/FAA
To: "Kimberly Mai" <Kimberly.Mai@faa.gov>
Date: 01/27/2012 09:40 AM
Subject: Fw: FCC Call Sign WE2XQQ Renewal FAA Coordination Request

Hi Kim,
FYI
Mark Gallant
Mgr, CSA Spectrum Engineering Team
817-222-4761-W
817-301-4505-C

From: "Thorsheim, Joel D" [Joel.D.Thorsheim@boeing.com]
Sent: 01/27/2012 07:35 AM PST
To: John Hepsen; Mark R Gallant
Subject: FW: FCC Call Sign WE2XQQ Renewal FAA Coordination Request

[John/Mark,](#)

Dan O 'Rear has given us the coordination for his areas excluding the 5250-5825 MHz band.

If you need anything else from me for this coordination request for Phoenix, Marana, and Roswell, please let me know.

I appreciate any help you can provide.

Joe

Joe Thorsheim
Frequency Management Services, M/C 2T-22
The Boeing Company
Phone: (206) 544-6066
Fax: (206) 662-0701

From: daniel.r.orear@faa.gov [<mailto:daniel.r.orear@faa.gov>]
Sent: Tuesday, January 24, 2012 11:55 AM
To: Thorsheim, Joel D
Cc: John.Hepsen@faa.gov; Mark.R.Gallant@faa.gov
Subject: Re: FCC Call Sign WE2XQQ Renewal FAA Coordination Request

Joe,

Finally back in the office from back to back travel weeks. Your contact for AZ is John Hepsen, and I've cc'd the manager for the Central Service Area, Mark Gallant to help you with the POC for NM.

In your attached, File Number: 0108-EX-ML-2011 Call Sign: WE2XQQ it lists in the special conditions (4) that "The frequency bands 5250-5825 MHz is NOT allowed for renewal of the license due to potential interference to Navy and the other Federal Government operations." Given that, I'm assuming you want us to coordinate on the only band left, which is 5150-5250 MHz.

Please let us know how you'd like to proceed.

Dan ORear
ATO Western Service Area
Northwest Mountain Region
Spectrum Engineering Services
425-227-2637

From: "Thorsheim, Joel D" <Joel.D.Thorsheim@boeing.com>
To: Daniel R ORear/ANM/FAA@FAA
Date: 01/17/2012 09:53 AM
Subject: FCC Call Sign WE2XQQ Renewal FAA Coordination Request

Dan,

We will be renewing FCC call sign WE2XQQ (attached) and we would like to request FAA coordination for this

renewal. This license supports wireless LAN testing onboard the aircraft.

Who would be the appropriate FAA contacts for the New Mexico and Arizona locations?

Thanks for any help you can provide and please let me know if you need any more information

Joe

Joe Thorsheim

Frequency Management Services, M/C 2T-22

The Boeing Company

Phone: (206) 544-6066

Fax: (206) 662-0701

[attachment "WE2XQQ.pdf" deleted by Kimberly Mai/ASW/FAA]