

To: Nathan Miller  
E-Mail: nathan.a.miller@boeing.com  
From: Leann Nguyen  
Date: November 27, 2012

Subject: FCC File# 0603-EX-PL-2012

---

Message:

Please submit the stop buzzer information including name and telephone number to terminate the system if having interference occurs.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of November 27, 2012 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 18639