Joe,

Special condition 8 seems to have been brought forward from an older license. This special condition can be removed from this license.

Dan ORear ATO Western Service Area Northwest Mountain Region Spectrum Engineering Services 425-227-2637

From:"Thorsheim, Joel D" <Joel.D.Thorsheim@boeing.com>To:Daniel R ORear/ANM/FAA@FAADate:11/16/2012 12:46 PMSubject:WE2XWG Top Hat Special Condition

Dan,

FCC license WE2XWG (attached) is for AEW&C RADAR and Interrogator ground testing at Moses Lake. Special Condition 8 restricts the test to "Top Hat" only. We are under the impression that this special condition has stayed on the license over time but is no longer a concern for the FAA.

Can you please either confirm that indeed the FAA still wants the Top Hat only special condition for a reason or can we remove that special condition altogether on WE2XWG?

Thanks and have a good weekend.

Joe

Joe Thorsheim Frequency Management Services, M/C 2T-22 The Boeing Company Phone: (206) 544-6066 Fax: (206) 662-0701