


Anthony Serafini

From: oetech@fccsun27w.fcc.gov
Sent: Tuesday, May 15, 2012 11:41 PM
To: Anthony Serafini
Subject: Coordination Request Complete for File Number: 0641-EX-PL-2011



[FCC Home](#) | [Search](#) | [RSS](#) | [Updates](#) | [E-Filing](#) | [Initiatives](#) | [Consumers](#) | [Find People](#)

Office of Engineering and Technology

All coordination requests for file number 0641-EX-PL-2011 have been given final status by OFACS. The FAS charge for this filing has now been closed.

Coordination Results:

NG Number	Status Code	Status Description	Condition Code	SCB Comments
NG 137053	66	Coordination Complete	2	NG T# HAS NOT BEEN RECEIVED FOR MORE THAN 30 DAYS.
NG 140197	66	Coordination Complete	2	N/A

Agreement Text:

NG Number	Notes	Agreement Text
NG 137053	PER CLEARANCE- USE OF THIS FRQ OR BAND UNDER THE AUTHORITY OF THIS ASSIGN IS SUBJ TO FURTHER COORDINATION WITH THE FAA EASTERN COORDINATOR, NEW YORK, NEW YORK, AS NECESSARY TO ENSURE COMPATIBILITY WITH EXISTING USES (C049);	\$\$ADD NG 137053 TYP01 N SEC01 05448 RVS01 05451 SER01 NG 137053 CLA01 U FRQ01 M1300.000000 NET01 ELS01 IPD01 120426 DEC01 ACCEPT BUR01 FCC EXD01 140531 STC01 XT EMS01 3M00Q3N PWR01 K48.66500 NTS01 C049 XSC01 MD XAL01 FULTON XRC01 10004233 XLA01 390909N XLG01 0765434W XCL01 WG 2XAV RSC01 MD RAL01 FULTON RLA01 390909N RLG01 0765434W REM01 *AGN,ELTA NORTH AMERICA REM02 *AGN,PWR IS ERP REM03 *AGN,APPLICANT SHALL BLANK TRANSMISSION REM04 *AGN,IN THE DIRECTION BETWEEN 0 DEGREES

		<p>REM05 *AGN,THROUGH 270 DEGREES REM06 *FLN,0641-EX-PL-2011 REM07 *PRR,3K/6K REM08 *EQT,C,ELTA EL/M-21066NG,PD22 SUP01 RADAR TESTING ELTA EL/M-21066NG RADAR PULSE RATE 3 OR 6 KHZ, PULSE WIDTH SUP02 22 USEC FAA COORDINATED NG T120098 MR. DON BRISTOL OF THE FAA SUP03 718-977-6611 ACL01 WG 2XAV DAT01 120420 LBO DATE: 02/17/2012 IRAC COMMENTS: APPROVED NTIA 05-09-2012 DATA CHANGES: FCC=>NTIA CHANGES ARE FRQ01:M1280=>M1300; EXD01:=>140531; NTS01:=>C049; SCB COMMENTS: PER CLEARANCE- USE OF THIS FRQ OR BAND UNDER THE AUTHORITY OF THIS ASSIGN IS SUBJ TO FURTHER COORDINATION WITH THE FAA EASTERN COORDINATOR, NEW YORK, NEW YORK, AS NECESSARY TO ENSURE COMPATIBILITY WITH EXISTING USES (C049); \$ IDKT: J0821773</p>
<p>NG 140197</p>	<p>PER CLEARANCE-UPON NOTIFICATION FROM THE FCC, OPERATION ON THIS ASSIGNMENT IS SUBJECT TO IMMEDIATE CESSATION, IF IT CAUSES HARMFUL INTERFERENCE TO N 937017 ASSIGNMENTS (M008); PER CLEARANCE- USE OF THIS FRQ OR BAND UNDER THE AUTHORITY OF THIS ASSIGN IS SUBJ TO FURTHER COORDINATION WITH THE FAA EASTERN COORDINATOR, NEW YORK, NEW YORK, AS NECESSARY TO ENSURE COMPATIBILITY WITH EXISTING USES (C049);</p>	<p>\$\$ADD NG 140197 TYP01 N SEC01 05448 RVS01 05453 SER01 NG 140197 CLA01 U FRQ01 M1355.000000 NET01 ELS01 IPD01 120430 DEC01 ACCEPT BUR01 FCC EXD01 140531 STC01 XT EMS01 3M00Q3N PWR01 K48.66500 NTS01 C049 XSC01 MD XAL01 FULTON XRC01 10004233 XLA01 390909N XLG01 0765434W XCL01 WG 2XAV RSC01 MD RAL01 FULTON RLA01 390909N RLG01 0765434W REM01 *AGN,ELTA NORTH AMERICA REM02 *AGN,APPLICANT SHALL BLANK TRANSMISSION REM03 *AGN,IN THE DIRECTION BETWEEN 0 DEGREES REM04 *AGN,THROUGH 270 DEGREES REM05 *AGN,PWR IS ERP REM06 *FLN,0641-EX-PL-2011 REM07 *PRR,3K/6K REM08 *EQT,C,EL/M-2106NG,PD22 REM09 *NTS,M008,N 937017 SUP01 RADAR TESTING ELTA EL/M-21066NG RADAR PULSE RATE 3 OR 6 KHZ, PULSE WIDTH SUP02 22 USEC FAA COORDINATED NG T120098 MR. DON BRISTOL OF THE FAA SUP03 718-977-6611 ACL01 WG 2XAV DAT01 120420 LBO DATE: 04/10/2012 IRAC COMMENTS: APPROVED NTIA 05-14-2012 DATA CHANGES: FCC=>NTIA CHANGES ARE EXD01:=>140531; NTS01:=>C049; SCB COMMENTS: PER CLEARANCE-UPON NOTIFICATION FROM THE FCC, OPERATION ON THIS ASSIGNMENT IS SUBJECT TO IMMEDIATE CESSATION, IF IT CAUSES HARMFUL INTERFERENCE TO N 937017 ASSIGNMENTS (M008); PER CLEARANCE- USE OF THIS FRQ OR BAND UNDER THE</p>

AUTHORITY OF THIS ASSIGN IS SUBJ TO FURTHER
COORDINATION WITH THE FAA EASTERN COORDINATOR, NEW
YORK, NEW YORK, AS NECESSARY TO ENSURE COMPATIBILITY
WITH EXISTING USES (C049); \$
IDKT: J0821774