

To: Michael Miller  
E-Mail: mlmiller@sterk.space  
From: Nimesh Sangani  
Date: March 04, 2021

Subject: Additional Information Request

---

Message:

Please address the following questions/concerns:

1. The emission designator in the Form 442 (16M0G1D) for the 8045 MHz Space-to-Earth link does not match that provided in the spacecap (8M00G1D). Request the applicant provide correction/clarification.
2. Will the cutting of the steel coupon be internal to the spacecraft (and will therefore contain the steel coupon and any shavings) or will there be any external components that may result in a release of debris?

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of March 04, 2021 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 60480