

To: Ronald Quirk  
E-Mail: req@commlawgroup.com  
From: Doug Young  
Date: March 20, 2017

Subject: Request for Info - File #0153-EX-CN-2016

---

Message:

The FCC's International Bureau needs clarification of the RF links in this system.

Question 1: Is the SD WiFi Hub operating in the aircraft cabin in the 1626.5-1669.5 MHz band or is the Satcom Direct Router a transmitter operating with the INMARSAT satellites (at GSO)?

Questions 2: If the Satcom Direct Router is the transmitter is it operating with INMARSAT satellites?

Question 3: If so, has Inmarsat approved the Satcom Direct Router as Inmarsat terminal previously?

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of March 20, 2017 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 36132