To: Richard Chin E-Mail: rchin@textronsystems.com From: Leann Nguyen Date: March 15, 2018

Subject: Request for Info - File # 0496-EX-ST-2018

Message:

Please submit the following information

- Emission designator. Your emission designator is incomplete. It is missing bandwidth information.
- Stop buzzer including name and telephone number.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of March 15, 2018 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at https://apps.fcc.gov/oetcf/els/index.cfm by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number: 41247