

To: Michael Miller  
E-Mail: mlmiller@sterk.space  
From: Leann Nguyen  
Date: May 06, 2021

Subject: Request for Info - File # 0159-EX-CN-2021

---

Message:

Please submit the following information

- In the emissions tab, for the downlinks, please check of the minimum power densities In the spacecap, in the emissions tab, the minimum power density for the downlink with designator 150HN1A is stated to be -30. A rough analysis shows the minimum power density closer to -15.7. Please provide an explanation or correct.

- The emission designator for the HF uplink does not match between the form 442 and the spacecap. Please indicate what the correct emission designator is and provide updated file(s).

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of May 06, 2021 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 61775