

To: Richard Eldridge  
E-Mail: richard\_eldridge@haci.honda.com  
From: Doug Young  
Date: July 02, 2012

Subject: Request for Info - STA File #0537-EX-ST-2012

---

Message:

Your antenna fails slope calculations from the FCC's TOWAIR program at <http://wireless2.fcc.gov/UlsApp/AsrSearch/towairSearch.jsp>. Submit a detailed justification for why you think this antenna does not need to be registered under 47CFR17.7.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of July 02, 2012 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 17355