

Reason for 2 NGT numbers for the southwest region.

The FAA Southwest Regional office issued 2 NGT numbers probably due to there being 2 transmitters, one on the ground and one in the air. It may also have to do with the distance we are planning on using the frequencies to(100KM). The eastern office did not issue 2 because the distance was so small.