

Claude

The following FAA assignments for your PSTAR program at Syracuse, NY (43-06-43N/076-11-18W) are still good until 07/30/2005. The same transmitter blanking bearings described in steps 7 thru 13 of FCC license (file # 0006-EX-ML-2004), that you sent me below, must still be followed.

1250 MHz	NG	038190
1260 MHz	NG	038191
1270 MHz	NG	038192
1280 MHz	NG	038193
1290 MHz	NG	038194
1340 MHz	NG	038195
1360 MHz	NG	038196
1370 MHz	NG	038197
1380 MHz	NG	039957
1390 MHz	NG	038198

John Mormino
Eastern Region
Spectrum Engineer (NISC)
718-977-6546