

Behnam Ghaffari

From: Ranveer Chandra [ranveer@microsoft.com]
Sent: Friday, March 11, 2011 3:31 PM
To: oetech@fccsun27w.fcc.gov; Behnam Ghaffari
Subject: RE: FCC File No. 0140-EX-ST-2011
Follow Up Flag: Follow up
Flag Status: Red

Dear Mr. Ghaffari,


Per our conversation, the devices in our setup will be fixed. Do let me know if you have further questions.

Thanks,
 Ranveer

From: oetech@fccsun27w.fcc.gov [mailto:oetech@fccsun27w.fcc.gov]
Sent: Friday, March 04, 2011 5:16 AM
To: Ranveer Chandra
Subject: FCC File No. 0140-EX-ST-2011



[FCC Home](#) | [Search](#) | [RSS](#) | [Updates](#) | [E-Filing](#) | [Initiatives](#) | [Consumers](#) | [Find P](#)

**Office of Engineering and Technology**

To: Ranveer Chandra, Microsoft Corporation
ranveer@microsoft.com
From: Behnam Ghaffari
Behnam.Ghaffari@fcc.gov

Applicant: Microsoft Corporation
File Number: 0140-EX-ST-2011
Correspondence Reference Number: 13170
Date of Original Email: 03/04/2011

You have requested for operation with an ERP of 2.43 watts, in which it does not comply with white spaces requirements. Please refer to power limits under the FCC CFR 47 Part 15.709 (a)(2) and adjust the ERP accordingly.

The items indicated above must be submitted before processing can continue on the above referenced

3/22/2011

application. Failure to provide the requested information within 30 days of 03/04/2011 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the reply button. In order for your response to be processed expeditiously, you must upload your response via the Internet by visiting [The OET Experimental Licensing System](#), followed by clicking on the "Reply to Correspondence" hyperlink.