

From: Steve Rovarino

To: Behnam Ghaffari

Date: April 22, 2019

Subject: 0628-EX-ST-2019

---

Message:

The original hardware technology had software issues. A known bug around random system reboots. We would like to re-test the same solution with the latest fixed software.

The previous test was a failure due to the hardware issues. Now that the product has been corrected we would like to re-run the test.