

To: Ryan Martineau
E-Mail: ryan.martineau@sdl.usu.edu
From: Doug Young
Date: March 19, 2018

Subject: Request for Info - File # 0759-EX-CN-2017

Message:

What is the status of fixing the SpaceCap error and submitting the antenna beam diagrams? Also, you have not changed the 450 MHz frequency to comply with another request for info.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of March 19, 2018 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 41295