

Miller (US), Nathan A

From: Vu.Pham@faa.gov
Sent: Monday, October 15, 2018 3:22 PM
To: Miller (US), Nathan A
Cc: Thomas.Ahn@faa.gov
Subject: RE: FAA Coordination - Experimental License WE2XSO

Nate,

Below is FAA coordination number for renewing XT license WE2XSO.

NG T180727	M1090.0000	RENTON	WA
NG T180728	M1030.0000	RENTON	WA
NG T180730	M1090.0000	SEATTLE	WA
NG T180729	M1030.0000	SEATTLE	WA
NG T180731	M1030.0000	EVERETT	WA
NG T180732	M1090.0000	EVERETT	WA

Regards,

Vu Pham
Spectrum Engineering Services
Western Service Area, AJW-1C7
Office Phone: (206) 231 4180
Email: vu.pham@faa.gov

From: Miller (US), Nathan A <Nathan.A.Miller@boeing.com>
Sent: Tuesday, September 25, 2018 1:14 PM
To: Pham, Vu (FAA) <Vu.Pham@faa.gov>
Subject: FAA Coordination - Experimental License WE2XSO

Good Afternoon,

I have a coordination request for you. I am renewing experimental license WE2XSO. I have attached the previous coordination and the current license. If you have any questions please let me know. Thanks!

Nate

Nathan A. Miller
Global Spectrum Management
(Formerly, Frequency Management Services)
+1 (206) 544-6045

