

To: Darryl Holtmeyer
E-Mail: darryl.j.holtmeyer@boeing.com
From: Leann Nguyen
Date: November 17, 2011

Subject: FCC File# 0571-EX-PL-2011

Message:

Please submit FAA coordination including NG T numbers and FAA Point-of-Contact.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of November 17, 2011 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://fjallfoss.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 15483