

12/18/13

Submitted by
Alan D. Parker
The Boeing Company
Frequency Management Services M/C 2T-22
P.O. Box 3707
Seattle, WA 98128-2207
703-465-3448 (office)
866-248-1493 (toll free)
FMSEAST@Boeing.com

OBJECTIVE

Add the following FAA coordinated frequencies

FREQ	SER#
M121.725	NGT130450
M122.025	NGT130450
M122.050	NGT130450
M122.075	NGT130450
M122.125	NGT130450
M122.175	NGT130450
M122.225	NGT130450
M122. 275	NGT130450
M122.325	NGT130450
M122.375	NGT130450
M122.425	NGT130450
M122.475	NGT130450
M122.575	NGT130450
M122.625	NGT130450
M122.675	NGT130450
M126.200	NGT130450
M134.100	NGT130450
M135.075	NGT130450

Request the following FCC controlled frequencies

M121.950
M122.700 – M123.075
M128.825 – M132.000
M136.500 – M136.975

12/18/13

Submitted by
Alan D. Parker
The Boeing Company
Frequency Management Services M/C 2T-22
P.O. Box 3707
Seattle, WA 98128-2207
703-465-3448 (office)
866-248-1493 (toll free)
FMSEAST@Boeing.com

Test Description

No technical changes in license WF2XYK.

New Stop Buzzer:

Lorraine M. Damerau, (610) 591-4188