

To: Scott Palo
E-Mail: palo@colorado.edu
From: Nimesh Sangani
Date: June 09, 2021

Subject: Additional Information Request

Message:

Please address the following questions and concerns.

- 1) Please correct the fatal errors(see report that I sent via email).
- 2) There appears to be a Spacecap to GIMS link problem as the antenna diagrams are not being seen.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of June 09, 2021 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 62575