



Ivy Biomedical Systems, Inc.

11 Business Park Drive

Branford, CT 06405

Toll Free 800 247 4614

Fax 203 481 8734

www.ivybiomedical.com

Federal Communications Commission (FCC)
Authorization and Evaluation Division
7435 Oakland Mills Rd
Columbia MD 21046-1609
USA

RE: Software Security Description

Date: January 11, 2022

To Whom it May Concern:

This letter confirms the software operation of the 580076, FCC ID Number: 2A3IX-WGS100 module.
Per the Software Define Radio requirements, this module:

1. The RF parameters of the device cannot be altered through software.
2. A third party cannot modify, configure, or load different software or make configurations changes that impact radio frequency parameters, such as frequency range, modulation type, output power, or other radio parameters.

Radio parameters are defined in software that is installed at the factory. Any software that is user updatable cannot change radio frequency parameters. The software that effects radio frequency parameters can only be installed at the factory. If non-US versions of the software are required, they are maintained by the grantee only and controlled to ensure that the devices are not operated within the US. All recipients of the product are required to operate the device in the country for which the software is certified. All hardware designs and software configurations required to operate the radio are propriety to the grantee and undisclosed to third parties.

Sincerely,

A handwritten signature in blue ink, appearing to read "Felicia Piel".

Felicia Piel
VP, Quality Assurance/Regulatory Affairs
felicia.piel@ivybiomedical.com
203-481-4183 (ext. 2019)