

8/25/2022

Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

SUBJECT: Change of ID

To Whom It May Concern:

This letter grants authorization for representative of Trellisware Technologies, Inc. (Trellisware) to apply to the FCC for a change in identification as specified under 47CFR section 2.933 of the FCC rules.

The original certification FCC ID SQG-60SIPT will remain valid.

This authorization applies to the Laird model 60-SIPT, FCC ID SQG-60SIPT. The original grant date was August 11, 2017.

Trellisware will be marketing the 60-SIPT module as a product under a new FCC Identifier. Trellisware's grantee code is 2AX6X and proposes that it be issued FCC Identifier 2AX6X2-1760 for the module.

Laird has no control or responsibility with regards to the installation and use of the 2AX6X2-1760 module in the products outlined by Trellisware. As a result, Trellisware takes ownership and responsibility for compliance of their products which include the 2AX6X2-1760 module.

The original test results, technical information and relevant documents continue to be representative of and applicable to the changed equipment. Any confidential information regarding the SQG-60SIPT module shared to various test and certification firms shall remain confidential amongst the parties involved and not be shared to other third parties (including Trellisware) unless authorized.

Sincerely,

Brian Petted Technology Leader Laird Connectivity P: 1-262-421-4974

E: brian.petted@lairdconnect.com