






Band12-10MHz-QPSK-23095-1-0-Low-30-1000--37.05-PASS




Band12-10MHz-QPSK-23095-1-0-Low-1000-5000--41.81-PASS




Band12-10MHz-QPSK-23095-1-0-Low-5000-12000--59.49-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.  
Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China  
Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com  
Scan code to check authenticity



Band12-10MHz-QPSK-23095-1-0-Low-12000-26500--44.29-PASS




Band12-10MHz-QPSK-23130-1-0-High-30-1000--37.56-PASS




Band12-10MHz-QPSK-23130-1-0-High-1000-5000--41.37-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.  
Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China  
Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com  
Scan code to check authenticity



Band12-10MHz-QPSK-23130-1-0-High-5000-12000--59.43-PASS




Band12-10MHz-QPSK-23130-1-0-High-12000-26500--44.62-PASS




Band12-10MHz-16QAM-23060-1-0-Low-30-1000--37.87-PASS






Band12-10MHz-16QAM-23060-1-0-Low-1000-5000--42.24-PASS




Band12-10MHz-16QAM-23060-1-0-Low-5000-12000--59.37-PASS




Band12-10MHz-16QAM-23060-1-0-Low-12000-26500--44.6-PASS






Band12-10MHz-16QAM-23095-1-0-Low-30-1000--37.23-PASS



Band12-10MHz-16QAM-23095-1-0-Low-1000-5000--41.28-PASS



Band12-10MHz-16QAM-23095-1-0-Low-5000-12000--59.22-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A &amp; 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band12-10MHz-16QAM-23095-1-0-Low-12000-26500--44.55-PASS




Band12-10MHz-16QAM-23130-1-0-High-30-1000--37.25-PASS




Band12-10MHz-16QAM-23130-1-0-High-1000-5000--41.47-PASS





Band12-10MHz-16QAM-23130-1-0-High-5000-12000--58.88-PASS



Band12-10MHz-16QAM-23130-1-0-High-12000-26500--44.7-PASS

