

Model Difference

Model : MA-3000HD, MR-600, BN-302, Pure-Sound 88 DSP, MA-5000,
MA-6000, MHDR518B, MHDR650B, MHDR670B, MR-500, MR-700, MR-800, MR-
900, MA-7000, MA-8000, PWB-20, U-3300, KA-2815, BT-3210, BT-3208E, BT-9925,
KA-5800, KA-6800, KA-3817,
BN-302, BN-304, BN-308, BN-310, BN-312, BN-920, BN-6200,
BN-6400, BN-6600, D05, D06, D03, D12, D13, D16, D15, D18, D33, D34, D35, D36,
D37, D38, D39, D40, D45, D46, D47, D48, D49, D50, PA-807, AP-705D, PA-51D,
PA-52, PA-63, PA-64, PA-215S, PA-220, PA-230, PA-550, PA-650, PA-118, D23,
D260, D339, PA-120,
PA-210, BN-6, PMX-60, PMX-80, PMX-1200, PMX-605, PMX-805, PMX-1205, BN-
3016, BN-165, BN-265, X7, PCV-2030, BN-450,
K-308, K-210, K-213, SW-12, SW-999, SW-9912, SW-9915, SW-112, SW-115, S112,
S115, TB-8, TB-12, TB-15, TH-8, TH-10, TH-12,
TH-15, TH-18, BM-12, BM-15, T-12, TF-8, TF-12, TF-15, TJ-12,
TJ-15

All the models are the same circuit and RF module, except the mode names.

Regards

Sincerely,

Client's signature

Client's signature: 

Client's name / title : [Libby Fang Johnston](#)/ PM

Contact information / address: [365N.BERRY ST, BREA, CA 92821, USA](#)