Shenzhen Gaobo Communication Technology Co., Ltd

Jun 08, 2023

Subject: Tuning and Adjustment of Signal booster, FCC ID: 2A99P-GB3CPA4

There are no external tuning adjustments, the amplifier is factory set not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Yours sincerely,

Peter Shi

Peter Shi