

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AACLX100FW
15-0219-220
October 19, 2015
Camero tech
Xaver 100

INTERNAL PHOTOGRAPHS




Figure 1. PCB with UWB Antenna

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AACLX100FW
15-0219-220
October 19, 2015
Camero tech
Xaver 100




Figure 2. Component Side of PCB

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AACLX100FW
15-0219-220
October 19, 2015
Camero tech
Xaver 100




Figure 3. Zigbee Radio

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AACLX100FW
15-0219-220
October 19, 2015
Camero tech
Xaver 100




Figure 4. UWB Radio # 1

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AACLX100FW
15-0219-220
October 19, 2015
Camero tech
Xaver 100




Figure 5. UWB Radio #2