

Request for Class II Permissive Change

FCC ID: 2AAODBMO700

Date: 23 January 2020

TO: Federal Communication Commission

Please be notified that we, the undersigned, Breville Pty Ltd declare that the reasons for this Class II permissive change are as below:

The difference between the product in original ID and current one is adding alternative one inverter and two IGBT


| Before | | | After | | |
|-----------|--------------------|---|-----------|-------------------|---|
| Part name | Type No. | manufacturer | Part name | Type No. | manufacturer |
| Inverter | MD-INV200 0-L0S | SONG RESEARCH Electronic Technology CO.,LTD | Inverter | MD-INV20 00-L4 | Guangdong Midea Kitchen Appliances Manufacturing Co.,Ltd |
| IGBT | IHW30N120 R3 | Infineon Technologies | IGBT 1 | IHW30N13 5R3 | Infineon Technologies |
| | | | IGBT 2 | IHW30N13 5R5 | Infineon Technologies |

Thank you.
Sincerely,

Name (Printed): John Lee

Title: Compliance Manager

Signature:



JOHN LEE 09/06/2020

On behalf of Company: Breville Pty Ltd