


Photographs of the Test Configuration

Radiated Emission Below 1GHz Test (Model: TBAM100)






Report No.: FR081801 Page: : 1 of 8



Radiated Emission Below 1GHz Test (Model: TBAM100)







Report No.: FR081801 Page: : 2 of 8



Radiated Emission Above 1GHz Test (Model: TBAM100)







Report No.: FR081801 Page: : 3 of 8



Radiated Emission Above 1GHz Test (Model: TBAM100)







Report No.: FR081801 Page: : 4 of 8



Radiated Emission Below 1GHz Test (Model: TBSL100)







Report No.: FR081801 Page: : 5 of 8



Radiated Emission Below 1GHz Test (Model: TBSL100)







Report No.: FR081801 Page: : 6 of 8



Radiated Emission Below 1GHz Test (Model: TBWL100)







Report No.: FR081801 Page: : 7 of 8



Radiated Emission Below 1GHz Test (Model: TBWL100)





Report No.: FR081801 Page: : 8 of 8