





**Equipment Photographs**

**(Internal)**



Equipment Photographs



(Internal)





**Equipment Photographs**



**(Internal)**






Equipment Photographs

(Internal)



**Equipment Photographs**


**(Internal)**







**Equipment Photographs**

**(Internal)**



Equipment Photographs



(Internal)





Equipment Photographs

(Internal)





**Equipment Photographs**

**(Internal)**







**Equipment Photographs**

**NFC antenna**



**(Internal)**





**Equipment Photographs**



**(Internal)**



Equipment Photographs

NFC antenna

(Internal)





---

# INTERTEK TESTING SERVICE

---

Report No.: HK20101072

## Equipment Photographs

(Internal)

