

---

---

# INTERTEK TESTING SERVICE


Report No: HK20100359

## Configuration Photographs

### Worst-Case Radiated Emissions

(Front View)

Wireless Charging + Bluetooth + NFC



---

---

# INTERTEK TESTING SERVICE


Report No: HK20100359

## Configuration Photographs

### Worst-Case Radiated Emissions

(Rear View)

### Wireless Charging + Bluetooth + NFC



---

---

# INTERTEK TESTING SERVICE


Report No: HK20100359

## Configuration Photographs

### Worst-Case Radiated Emissions

(Front View)

### USB Charging + Bluetooth + NFC



---

---

# INTERTEK TESTING SERVICE


Report No: HK20100359

## Configuration Photographs

### Worst-Case Radiated Emissions

(Rear View)

### USB Charging + Bluetooth + NFC



---

---

# INTERTEK TESTING SERVICE


Report No: HK20100359

## Configuration Photographs

### Worst-Case Radiated Emissions

(Front View)

#### Wireless Charging + Bluetooth + Chip Insert



---

---

# INTERTEK TESTING SERVICE


Report No: HK20100359

## Configuration Photographs

### Worst-Case Radiated Emissions

(Rear View)

Wireless Charging + Bluetooth + Chip Insert



---

---

# INTERTEK TESTING SERVICE

Report No: HK20100359

## Configuration Photographs

### Worst-Case Radiated Emissions

(Front View)

USB Charging + Bluetooth + Chip Insert



---

---

# INTERTEK TESTING SERVICE

Report No: HK20100359

## Configuration Photographs

### Worst-Case Radiated Emissions

(Rear View)

USB Charging + Bluetooth + Chip Insert

