



15:24:18 25.08.2021

Band17-5MHz-QPSK-23790-25RB#0




15:24:43 25.08.2021

Band17-5MHz-QPSK-23825-1RB#0




15:25:09 25.08.2021

Band17-5MHz-QPSK-23825-25RB#0




15:25:34 25.08.2021

Band17-5MHz-16QAM-23755-1RB#0




15:23:40 25.08.2021

Band17-5MHz-16QAM-23755-25RB#0




15:24:05 25.08.2021

Band17-5MHz-16QAM-23790-1RB#0




15:24:31 25.08.2021

Band17-5MHz-16QAM-23790-25RB#0




15:24:56 25.08.2021

Band17-5MHz-16QAM-23825-1RB#0




15:25:21 25.08.2021

Band17-5MHz-16QAM-23825-25RB#0




15:25:46 25.08.2021

Band17-10MHz-QPSK-23780-1RB#0




15:51:19 25.08.2021

Band17-10MHz-QPSK-23780-50RB#0




15:51:44 25.08.2021

Band17-10MHz-QPSK-23790-1RB#0




15:52:10 25.08.2021

Band17-10MHz-QPSK-23790-50RB#0




15:52:34 25.08.2021

Band17-10MHz-QPSK-23800-1RB#0




15:53:00 25.08.2021

Band17-10MHz-QPSK-23800-50RB#0




15:53:25 25.08.2021

Band17-10MHz-16QAM-23780-1RB#0




15:51:31 25.08.2021

Band17-10MHz-16QAM-23780-50RB#0




15:51:56 25.08.2021

Band17-10MHz-16QAM-23790-1RB#0




15:52:22 25.08.2021

Band17-10MHz-16QAM-23790-50RB#0




15:52:47 25.08.2021

Band17-10MHz-16QAM-23800-1RB#0




15:53:13 25.08.2021

Band17-10MHz-16QAM-23800-50RB#0




15:53:37 25.08.2021

Band25-1.4MHz-QPSK-26047-1RB#0




19:06:30 15.11.2021

Band25-1.4MHz-QPSK-26047-6RB#0




19:06:54 15.11.2021

Band25-1.4MHz-QPSK-26365-1RB#0




19:07:21 15.11.2021

Band25-1.4MHz-QPSK-26365-6RB#0




19:07:46 15.11.2021

Band25-1.4MHz-QPSK-26683-1RB#0




19:08:12 15.11.2021

Band25-1.4MHz-QPSK-26683-6RB#0




19:08:36 15.11.2021

Band25-1.4MHz-16QAM-26047-1RB#0




19:06:42 15.11.2021

Band25-1.4MHz-16QAM-26047-6RB#0




19:07:07 15.11.2021

Band25-1.4MHz-16QAM-26365-1RB#0




19:07:33 15.11.2021

Band25-1.4MHz-16QAM-26365-6RB#0




19:07:58 15.11.2021

Band25-1.4MHz-16QAM-26683-1RB#0




19:08:24 15.11.2021

Band25-1.4MHz-16QAM-26683-6RB#0




19:08:49 15.11.2021

Band25-3MHz-QPSK-26055-1RB#0




19:35:01 15.11.2021

Band25-3MHz-QPSK-26055-15RB#0




19:35:26 15.11.2021

Band25-3MHz-QPSK-26365-1RB#0




19:35:53 15.11.2021

Band25-3MHz-QPSK-26365-15RB#0




19:36:17 15.11.2021

Band25-3MHz-QPSK-26675-1RB#0




19:36:44 15.11.2021

Band25-3MHz-QPSK-26675-15RB#0




19:37:08 15.11.2021

Band25-3MHz-16QAM-26055-1RB#0




19:35:14 15.11.2021

Band25-3MHz-16QAM-26055-15RB#0




19:35:38 15.11.2021

Band25-3MHz-16QAM-26365-1RB#0




19:36:05 15.11.2021

Band25-3MHz-16QAM-26365-15RB#0




19:36:29 15.11.2021

Band25-3MHz-16QAM-26675-1RB#0




19:36:56 15.11.2021

Band25-3MHz-16QAM-26675-15RB#0




19:37:21 15.11.2021

Band25-5MHz-QPSK-26065-1RB#0




20:04:12 15.11.2021

Band25-5MHz-QPSK-26065-25RB#0




20:04:37 15.11.2021

Band25-5MHz-QPSK-26365-1RB#0




20:05:03 15.11.2021

Band25-5MHz-QPSK-26365-25RB#0




20:05:28 15.11.2021

Band25-5MHz-QPSK-26665-1RB#0




20:05:54 15.11.2021

Band25-5MHz-QPSK-26665-25RB#0




20:06:19 15.11.2021

Band25-5MHz-16QAM-26065-1RB#0




20:04:25 15.11.2021

Band25-5MHz-16QAM-26065-25RB#0




20:04:49 15.11.2021

Band25-5MHz-16QAM-26365-1RB#0




20:05:15 15.11.2021

Band25-5MHz-16QAM-26365-25RB#0




20:05:40 15.11.2021

Band25-5MHz-16QAM-26665-1RB#0




20:06:06 15.11.2021

Band25-5MHz-16QAM-26665-25RB#0




20:06:31 15.11.2021

Band25-10MHz-QPSK-26090-1RB#0




20:32:36 15.11.2021

Band25-10MHz-QPSK-26090-50RB#0




20:33:01 15.11.2021

Band25-10MHz-QPSK-26365-1RB#0




20:33:27 15.11.2021

Band25-10MHz-QPSK-26365-50RB#0




20:33:52 15.11.2021

Band25-10MHz-QPSK-26640-1RB#0




20:34:19 15.11.2021

Band25-10MHz-QPSK-26640-50RB#0




20:34:44 15.11.2021

Band25-10MHz-16QAM-26090-1RB#0




20:32:48 15.11.2021

Band25-10MHz-16QAM-26090-50RB#0




20:33:13 15.11.2021

Band25-10MHz-16QAM-26365-1RB#0




20:33:40 15.11.2021

Band25-10MHz-16QAM-26365-50RB#0




20:34:05 15.11.2021

Band25-10MHz-16QAM-26640-1RB#0




20:34:31 15.11.2021

Band25-10MHz-16QAM-26640-50RB#0




20:34:56 15.11.2021

Band25-15MHz-QPSK-26115-1RB#0




21:01:46 15.11.2021

Band25-15MHz-QPSK-26115-75RB#0




21:02:11 15.11.2021

Band25-15MHz-QPSK-26365-1RB#0




21:02:38 15.11.2021

Band25-15MHz-QPSK-26365-75RB#0




21:03:04 15.11.2021

Band25-15MHz-QPSK-26615-1RB#0




21:03:31 15.11.2021

Band25-15MHz-QPSK-26615-75RB#0




21:03:56 15.11.2021

Band25-15MHz-16QAM-26115-1RB#0




21:01:58 15.11.2021

Band25-15MHz-16QAM-26115-75RB#0




21:02:24 15.11.2021

Band25-15MHz-16QAM-26365-1RB#0




21:02:51 15.11.2021

Band25-15MHz-16QAM-26365-75RB#0




21:03:16 15.11.2021

Band25-15MHz-16QAM-26615-1RB#0




21:03:43 15.11.2021

Band25-15MHz-16QAM-26615-75RB#0




21:04:09 15.11.2021

Band25-20MHz-QPSK-26140-1RB#0




21:31:46 15.11.2021

Band25-20MHz-QPSK-26140-100RB#0




21:32:13 15.11.2021

Band25-20MHz-QPSK-26365-1RB#0




21:32:41 15.11.2021

Band25-20MHz-QPSK-26365-100RB#0




21:33:08 15.11.2021

Band25-20MHz-QPSK-26590-1RB#0




21:33:36 15.11.2021

Band25-20MHz-QPSK-26590-100RB#0




21:34:03 15.11.2021

Band25-20MHz-16QAM-26140-1RB#0




21:32:00 15.11.2021

Band25-20MHz-16QAM-26140-100RB#0




21:32:27 15.11.2021

Band25-20MHz-16QAM-26365-1RB#0




21:32:55 15.11.2021

Band25-20MHz-16QAM-26365-100RB#0




21:33:21 15.11.2021

Band25-20MHz-16QAM-26590-1RB#0




21:33:49 15.11.2021

Band25-20MHz-16QAM-26590-100RB#0




21:34:16 15.11.2021




Band26-1.4MHz-QPSK-26740-6RB#0

Band26-1.4MHz-QPSK-26915-6RB#0




Band26-1.4MHz-16QAM-26740-6RB#0

Band26-1.4MHz-16QAM-26915-6RB#0




Band26-3MHz-QPSK-26740-15RB#0

Band26-3MHz-QPSK-26915-15RB#0




Band26-3MHz-16QAM-26740-15RB#0


Band26-3MHz-16QAM-26915-15RB#0




Band26-5MHz-QPSK-26740-25RB#0

Band26-5MHz-QPSK-26915-25RB#0







Band26-15MHz-QPSK-26765-75RB#0



Band26-15MHz-QPSK-26915-75RB#0




Band38-5MHz-QPSK-37775-1RB#0




23:44:07 15.11.2021

Band38-5MHz-QPSK-37775-25RB#0




23:44:32 15.11.2021

Band38-5MHz-QPSK-38000-1RB#0




23:44:58 15.11.2021

Band38-5MHz-QPSK-38000-25RB#0




23:45:23 15.11.2021

Band38-5MHz-QPSK-38225-1RB#0




23:45:49 15.11.2021

Band38-5MHz-QPSK-38225-25RB#0




23:46:13 15.11.2021

Band38-5MHz-16QAM-37775-1RB#0




23:44:20 15.11.2021

Band38-5MHz-16QAM-37775-25RB#0




23:44:44 15.11.2021

Band38-5MHz-16QAM-38000-1RB#0




23:45:10 15.11.2021

Band38-5MHz-16QAM-38000-25RB#0




23:45:35 15.11.2021

Band38-5MHz-16QAM-38225-1RB#0




23:46:01 15.11.2021

Band38-5MHz-16QAM-38225-25RB#0



23:46:25 15.11.2021

Band38-10MHz-QPSK-37800-1RB#0



13:27:24 16.11.2021

Band38-10MHz-QPSK-37800-50RB#0