



15:08:31 25.08.2021

Band17-10MHz-QPSK-23780-50RB#0



15:34:51 25.08.2021

Band17-10MHz-QPSK-23790-50RB#0




15:35:19 25.08.2021

Band17-10MHz-QPSK-23800-50RB#0




15:35:48 25.08.2021

Band17-10MHz-16QAM-23780-50RB#0




15:35:04 25.08.2021

Band17-10MHz-16QAM-23790-50RB#0




15:35:33 25.08.2021

Band17-10MHz-16QAM-23800-50RB#0




15:36:02 25.08.2021

Band25-1.4MHz-QPSK-26047-6RB#0




13:22:54 12.01.2022

Band25-1.4MHz-QPSK-26365-6RB#0




18:49:56 15.11.2021

Band25-1.4MHz-QPSK-26683-6RB#0




18:50:25 15.11.2021

Band25-1.4MHz-16QAM-26047-6RB#0




18:49:40 15.11.2021

Band25-1.4MHz-16QAM-26365-6RB#0




18:50:09 15.11.2021

Band25-1.4MHz-16QAM-26683-6RB#0




18:50:38 15.11.2021

Band25-3MHz-QPSK-26055-15RB#0




19:18:02 15.11.2021

Band25-3MHz-QPSK-26365-15RB#0




19:18:30 15.11.2021

Band25-3MHz-QPSK-26675-15RB#0




19:18:59 15.11.2021

Band25-3MHz-16QAM-26055-15RB#0




19:18:15 15.11.2021

Band25-3MHz-16QAM-26365-15RB#0




19:18:43 15.11.2021

Band25-3MHz-16QAM-26675-15RB#0




19:19:12 15.11.2021

Band25-5MHz-QPSK-26065-25RB#0




19:46:39 15.11.2021

Band25-5MHz-QPSK-26365-25RB#0




19:47:21 15.11.2021

Band25-5MHz-QPSK-26665-25RB#0




19:48:04 15.11.2021

Band25-5MHz-16QAM-26065-25RB#0




19:46:59 15.11.2021

Band25-5MHz-16QAM-26365-25RB#0




19:47:42 15.11.2021

Band25-5MHz-16QAM-26665-25RB#0




19:48:24 15.11.2021

Band25-10MHz-QPSK-26090-50RB#0




20:15:15 15.11.2021


Band25-10MHz-QPSK-26365-50RB#0



Band25-10MHz-QPSK-26640-50RB#0




Band25-10MHz-16QAM-26090-50RB#0




20:15:28 15.11.2021

Band25-10MHz-16QAM-26365-50RB#0




20:15:57 15.11.2021

Band25-10MHz-16QAM-26640-50RB#0




20:16:26 15.11.2021

Band25-15MHz-QPSK-26115-75RB#0




20:44:03 15.11.2021

Band25-15MHz-QPSK-26365-75RB#0




20:44:32 15.11.2021

Band25-15MHz-QPSK-26615-75RB#0




20:45:01 15.11.2021

Band25-15MHz-16QAM-26115-75RB#0




20:44:16 15.11.2021

Band25-15MHz-16QAM-26365-75RB#0




20:44:46 15.11.2021

Band25-15MHz-16QAM-26615-75RB#0




20:45:15 15.11.2021

Band25-20MHz-QPSK-26140-100RB#0




21:13:36 15.11.2021

Band25-20MHz-QPSK-26365-100RB#0




21:14:06 15.11.2021

Band25-20MHz-QPSK-26590-100RB#0




21:14:37 15.11.2021

Band25-20MHz-16QAM-26140-100RB#0




21:13:51 15.11.2021

Band25-20MHz-16QAM-26365-100RB#0




21:14:21 15.11.2021


Band25-20MHz-16QAM-26590-100RB#0



21:14:51 15.11.2021




Band26-1.4MHz-QPSK-26697-6RB#0



Band26-1.4MHz-QPSK-26740-6RB#0



Band26-1.4MHz-QPSK-26783-6RB#0




Band26-1.4MHz-QPSK-26797-6RB#0



Band26-1.4MHz-QPSK-26915-6RB#0





Band26-1.4MHz-QPSK-27033-6RB#0





Band26-1.4MHz-16QAM-26697-6RB#0

Band26-1.4MHz-16QAM-26740-6RB#0









Band26-1.4MHz-16QAM-26783-6RB#0

Band26-1.4MHz-16QAM-26797-6RB#0




Band26-1.4MHz-16QAM-26915-6RB#0

Band26-1.4MHz-16QAM-27033-6RB#0




Band26-3MHz-QPSK-26915-15RB#0


Band26-3MHz-QPSK-27025-15RB#0




Band26-3MHz-16QAM-26705-15RB#0




Band26-3MHz-16QAM-26740-15RB#0




Band26-3MHz-16QAM-26775-15RB#0




Band26-3MHz-16QAM-26805-15RB#0




Band26-3MHz-16QAM-26915-15RB#0




Band26-3MHz-16QAM-27025-15RB#0




Band26-5MHz-QPSK-26715-25RB#0




Band26-5MHz-QPSK-26740-25RB#0




Band26-5MHz-QPSK-26765-25RB#0




Band26-5MHz-QPSK-26815-25RB#0




Band26-5MHz-QPSK-26915-25RB#0




Band26-5MHz-QPSK-27015-25RB#0




Band26-5MHz-16QAM-26715-25RB#0




Band26-5MHz-16QAM-26740-25RB#0




Band26-5MHz-16QAM-26765-25RB#0









Band26-5MHz-16QAM-26815-25RB#0



Band26-5MHz-16QAM-26915-25RB#0




Band26-5MHz-16QAM-27015-25RB#0




Band26-10MHz-16QAM-26740-50RB#0

Band26-10MHz-16QAM-26840-50RB#0




Band26-10MHz-16QAM-26915-50RB#0




Band26-10MHz-16QAM-26990-50RB#0




Band26-15MHz-QPSK-26765-75RB#0




Band26-15MHz-QPSK-26865-75RB#0




Band26-15MHz-QPSK-26915-75RB#0




Band26-15MHz-QPSK-26965-75RB#0




Band26-15MHz-16QAM-26765-75RB#0



Band26-15MHz-16QAM-26865-75RB#0




Band26-15MHz-16QAM-26915-75RB#0



Band26-15MHz-16QAM-26965-75RB#0

Band38-5MHz-QPSK-37775-25RB#0




23:26:26 15.11.2021

Band38-5MHz-QPSK-38000-25RB#0




23:27:09 15.11.2021

Band38-5MHz-QPSK-38225-25RB#0




23:27:52 15.11.2021

Band38-5MHz-16QAM-37775-25RB#0




23:26:46 15.11.2021

Band38-5MHz-16QAM-38000-25RB#0




23:27:30 15.11.2021

Band38-5MHz-16QAM-38225-25RB#0




23:28:13 15.11.2021

Band38-10MHz-QPSK-37800-50RB#0




09:54:57 18.01.2022

Band38-10MHz-QPSK-38000-50RB#0




09:55:36 18.01.2022

Band38-10MHz-QPSK-38200-50RB#0




09:56:15 18.01.2022

Band38-10MHz-16QAM-37800-50RB#0




09:55:15 18.01.2022

Band38-10MHz-16QAM-38000-50RB#0




09:55:54 18.01.2022

Band38-10MHz-16QAM-38200-50RB#0




09:56:33 18.01.2022

Band38-15MHz-QPSK-37825-75RB#0




08:54:38 18.01.2022

Band38-15MHz-QPSK-38000-75RB#0




08:55:05 18.01.2022

Band38-15MHz-QPSK-38175-75RB#0




08:55:42 18.01.2022

Band38-15MHz-16QAM-37825-75RB#0




08:54:50 18.01.2022

Band38-15MHz-16QAM-38000-75RB#0




08:55:16 18.01.2022

Band38-15MHz-16QAM-38175-75RB#0




08:55:54 18.01.2022

Band38-20MHz-QPSK-37850-100RB#0




09:57:19 18.01.2022

Band38-20MHz-QPSK-38000-100RB#0




09:57:47 18.01.2022

Band38-20MHz-QPSK-38150-100RB#0




09:58:28 18.01.2022

Band38-20MHz-16QAM-37850-100RB#0




09:57:32 18.01.2022

Band38-20MHz-16QAM-38000-100RB#0




09:58:00 18.01.2022


Band38-20MHz-16QAM-38150-100RB#0




09:58:41 18.01.2022




Band40-5MHz-QPSK-38725-25RB#0




Band40-5MHz-QPSK-38750-25RB#0




Band40-5MHz-QPSK-38775-25RB#0




Band40-5MHz-QPSK-39175-25RB#0




Band40-5MHz-QPSK-39200-25RB#0




Band40-5MHz-QPSK-39225-25RB#0




Band40-5MHz-16QAM-38725-25RB#0




Band40-5MHz-16QAM-38750-25RB#0




Band40-5MHz-16QAM-38775-25RB#0





Band40-5MHz-16QAM-39175-25RB#0



Band40-5MHz-16QAM-39200-25RB#0





Band40-5MHz-16QAM-39225-25RB#0



Band40-10MHz-QPSK-38750-50RB#0


Band40-10MHz-QPSK-39200-50RB#0



Band40-10MHz-16QAM-38750-50RB#0


Band40-10MHz-16QAM-39200-50RB#0

Band41-5MHz-QPSK-39675-25RB#0



21:02:45 17.01.2022

Band41-5MHz-QPSK-40620-25RB#0




21:03:52 17.01.2022

Band41-5MHz-QPSK-41565-25RB#0




21:04:59 17.01.2022

Band41-5MHz-16QAM-39675-25RB#0




21:03:17 17.01.2022

Band41-5MHz-16QAM-40620-25RB#0




21:04:24 17.01.2022

Band41-5MHz-16QAM-41565-25RB#0




21:05:31 17.01.2022

Band41-10MHz-QPSK-39700-50RB#0




21:06:06 17.01.2022

Band41-10MHz-QPSK-40620-50RB#0




21:06:36 17.01.2022

Band41-10MHz-QPSK-41540-50RB#0




21:07:07 17.01.2022

Band41-10MHz-16QAM-39700-50RB#0




21:06:20 17.01.2022

Band41-10MHz-16QAM-40620-50RB#0




21:06:49 17.01.2022

Band41-10MHz-16QAM-41540-50RB#0




21:07:20 17.01.2022

Band41-15MHz-QPSK-39725-75RB#0




08:49:27 19.01.2022

Band41-15MHz-QPSK-40620-75RB#0




08:49:58 19.01.2022

Band41-15MHz-QPSK-41515-75RB#0




08:50:29 19.01.2022

Band41-15MHz-16QAM-39725-75RB#0




08:49:40 19.01.2022

Band41-15MHz-16QAM-40620-75RB#0




08:50:11 19.01.2022

Band41-15MHz-16QAM-41515-75RB#0




08:50:42 19.01.2022

Band41-20MHz-QPSK-39750-100RB#0




08:51:18 19.01.2022

Band41-20MHz-QPSK-40620-100RB#0




08:51:47 19.01.2022

Band41-20MHz-QPSK-41490-100RB#0



08:52:19 19.01.2022

Band41-20MHz-16QAM-39750-100RB#0




08:51:32 19.01.2022

Band41-20MHz-16QAM-40620-100RB#0




08:52:01 19.01.2022

Band41-20MHz-16QAM-41490-100RB#0




08:52:32 19.01.2022

Band66-1.4MHz-QPSK-131979-6RB#0




08:40:40 18.01.2022

Band66-1.4MHz-QPSK-132322-6RB#0




08:41:06 18.01.2022

Band66-1.4MHz-QPSK-132665-6RB#0




08:41:33 18.01.2022

Band66-1.4MHz-16QAM-131979-6RB#0




08:40:51 18.01.2022

Band66-1.4MHz-16QAM-132322-6RB#0



08:41:18 18.01.2022

Band66-1.4MHz-16QAM-132665-6RB#0




08:41:45 18.01.2022

Band66-3MHz-QPSK-131987-15RB#0




14:41:10 26.08.2021

Band66-3MHz-QPSK-132322-15RB#0




14:41:38 26.08.2021

Band66-3MHz-QPSK-132657-15RB#0




14:42:07 26.08.2021

Band66-3MHz-16QAM-131987-15RB#0




14:41:24 26.08.2021

Band66-3MHz-16QAM-132322-15RB#0




14:41:52 26.08.2021

Band66-3MHz-16QAM-132657-15RB#0




14:42:20 26.08.2021

Band66-5MHz-QPSK-131997-25RB#0




15:07:43 26.08.2021

Band66-5MHz-QPSK-132322-25RB#0




15:08:26 26.08.2021

Band66-5MHz-QPSK-132647-25RB#0




15:09:08 26.08.2021

Band66-5MHz-16QAM-131997-25RB#0




15:08:04 26.08.2021

Band66-5MHz-16QAM-132322-25RB#0




15:08:46 26.08.2021

Band66-5MHz-16QAM-132647-25RB#0




15:09:28 26.08.2021

Band66-10MHz-QPSK-132022-50RB#0




15:34:49 26.08.2021

Band66-10MHz-QPSK-132322-50RB#0



15:35:17 26.08.2021

Band66-10MHz-QPSK-132622-50RB#0




15:35:46 26.08.2021

Band66-10MHz-16QAM-132022-50RB#0




15:35:02 26.08.2021

Band66-10MHz-16QAM-132322-50RB#0




15:35:31 26.08.2021

Band66-10MHz-16QAM-132622-50RB#0



15:36:00 26.08.2021

Band66-15MHz-QPSK-132047-75RB#0




16:02:19 26.08.2021

Band66-15MHz-QPSK-132322-75RB#0



16:02:49 26.08.2021

Band66-15MHz-QPSK-132597-75RB#0




16:03:18 26.08.2021

Band66-15MHz-16QAM-132047-75RB#0




16:02:33 26.08.2021

Band66-15MHz-16QAM-132322-75RB#0




16:03:02 26.08.2021

Band66-15MHz-16QAM-132597-75RB#0



16:03:32 26.08.2021

Band66-20MHz-QPSK-132072-100RB#0




16:29:52 26.08.2021

Band66-20MHz-QPSK-132322-100RB#0




16:30:21 26.08.2021

Band66-20MHz-QPSK-132572-100RB#0



16:30:51 26.08.2021

Band66-20MHz-16QAM-132072-100RB#0




16:30:06 26.08.2021

Band66-20MHz-16QAM-132322-100RB#0



16:30:35 26.08.2021

Band66-20MHz-16QAM-132572-100RB#0



16:31:05 26.08.2021

