


SETUP PHOTOS 11.

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP




RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)






RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)






POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH USB LAPTOP



Page 137 of 139



POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH AC ADAPTER



Page 138 of 139



END OF REPORT